

REPORT OF  
NEWMONT POWER PTY LTD  
PURSUANT TO THE  
ELECTRICITY INDUSTRY (NETWORK QUALITY AND RELIABILITY OF  
SUPPLY) CODE 2005  
FOR THE PERIOD  
1 JANUARY 2006 TO 30 JUNE 2006  
WITH RESPECT TO  
DISTRIBUTION LICENCE EDL4

Newmont Power Pty Ltd owns approximately 20km of distribution system radiating from the Parkeston Power Station near Kalgoorlie.

Two customers are connected to the distribution network, neither of which are small-use customers. The network contains no metering equipment and no circuit breakers for the automatic interruption of power to customers.

The contracts between the customers and Newmont Power Pty Ltd (pre-dating the coming into effect of the Code) contain provisions relating to quality of supply and interruptions, satisfying the requirements of Section 15(1) of the Code, including arrangements as to disputation. These contracts do not require Newmont Power Pty Ltd to have in place a system to measure compliance with any quality or interruption standards.

Newmont Power Pty Ltd understands that, pursuant to section 28(2) of the code it must, for the period in question, report on items 11 to 15 of Schedule 1 of the Code. This information is set out below using the same numbering scheme as contained in Schedule 1:

11. The network is located in only one area, the Kalgoorlie-Boulder LGA. The network suffered no interruptions in the reporting period.
  - (a) 0 minutes
  - (b) 0
  - (c) 100%
  - (d) 0 minutes
12. Information relating to the 3 preceding years is not available
13. This information is not calculable as information relating to the 3 preceding years is not available.
14. As there are only 2 customer premises the information at the various percentile levels is not calculable.
15. As per 14

As Newmont Power Pty Ltd's arrangements with its customers do not require a system to monitor its compliance with respect to Part 2 of the Code or with any standards prescribed in accordance with Section 15(1), no audit of these systems is possible, and as a result Newmont Power Pty Ltd is unable to arrange for the preparation of an independent audit report as may be prescribed by Section 26.